

WO #: PE77937

WO Desc: LDAR-Repair AVO visual leak on M-200 loading fire valve packing. 045A on dwg STF-05. See attached.

Parent WO#:

WO Long Desc:

WO Priority: 2

Location: I-A-M210

MONOMER TANK 2 BARGE DOCK INLET FIRE VALVE

Asset: 5302201

MONOMER TANK 2 BARGE DOCK INLET FIRE VALVE

Asset Service:

Entry Date: 11/27/2017

WO Status: CLOSE

Action Code: LDAR

Project #:

Originator: ADAM CHAPMAN

Status Date: 5/29/2018

Work Type: CM

Failure Class: FIXDVLV

Job Plan:

Planned Start:

Actual Start: 11/29/2017

Review Date:

PM/Bundle:

Planned Completion: 12/19/2017

Actual Completion: 11/29/2017

Plant Information

RC: PERC01

Planner: WILLIAM STONEKING

MOC#:

When Code: RT

Lead Craft: MECH

MOC Status:

P&ID:

MOC Desc:

SIR/EIS Required:

LDAR

Tag #:

1st Attempt Made:

LDAR Planning Notes:

Leak Type:

1st Attempt Was:

LDAR Additional Notes:

Size:

1st Attempt Due By: 12/2/2017

Leak Location:

After 1st Attempt PPM:

Location Orientation:

Final Due By: 12/12/2017

Completed by Emp #: _____

Signature: _____